

## City of Concord

Legislation Text

File #: 18-028, Version: 1

Report from the Traffic Engineer on behalf of the Traffic Operations Committee recommending the installation of a street light on an existing utility pole on the northeast corner of the North State Street/Franklin Street roundabout.